Mayflower Incident Unified Command Joint Information Center

CONTACT: 703-846-4467

For Immediate Release: April 6, 2013

Cleanup Operations Progress in Mayflower, AR

MAYFLOWER, AR – The Mayflower Incident Unified Command Joint Information Center provided the following update as cleanup operations continued Saturday following a release of crude oil near Mayflower, AR.

- Progress continues in the cleanup areas of the North Woods subdivision, an area between
 Main St. and the interstate highway, and a marsh area between the interstate highway and a
 cove adjacent to Lake Conway. The main body Lake Conway remains oil free. A
 comprehensive containment system using boom has been deployed as a precaution. The
 response operation has continued 24 hours a day since the spill was first detected
- Oil is being cleaned up through a combination of vacuum trucks, pressure washing, use of absorbent pads and removal of contaminated soil and vegetation.
- Most of the impacted soil has been removed from the yards of the six homes impacted by
 the spill in the North Woods subdivision. Work will continue as weather permits to enable
 residents to return as quickly as possible to 22 homes evacuated on Starlite Road and
 Shade Tree Lane. The Unified Command is hopeful that four days of forecasted good
 weather will help accelerate clean-up efforts.
- Air quality monitoring is being conducted by the U.S. Environmental Protection Agency and ExxonMobil separately, and data are being reviewed by the Arkansas Department of Health (ADH). Data from the air monitors outside the immediate work areas in the Mayflower community continue to show levels that are either non-detect or that are below any necessary action levels. Workers in the immediate cleanup areas have air quality monitoring and breathing equipment for use, if necessary. Air data are posted on the Arkansas Department of Environmental Quality's website and updated as it becomes available. http://www.adeq.state.ar.us/hazwaste/mayflower oil spill 2013/default.htm
- There has been no impact on Mayflower's drinking water supply. Community Water System
 manages the Mayflower's water supply, which is sourced from Greer's Ferry Lake, located
 about 65 miles northeast of Mayflower.
- An excavation and removal plan for the affected portion of the pipeline has been submitted for review by the U.S. Department of Transportation. ExxonMobil has received a corrective action order from the Pipeline and Hazardous Materials Safety Administration.
- Eighteen vacuum trucks and 59 storage tanks are on site. About 700 people are responding to the incident including federal, state and local responders.
- A claims hotline (1-800-876-9291) has been established for residents affected by the spill to register a claim and get more information. About 147 claims have been made to date.
- ExxonMobil is paying for the cleanup and will honor all valid claims. Reports to the contrary are inaccurate.

- U.S. Environmental Services, an ExxonMobil contractor, has a wildlife rehabilitation operation on site and is working with Animal Response Services on a treatment program. Affected wildlife includes ducks, turtles, a beaver and a muskrat. Thirteen dead ducks, one dead nutria, and three dead turtles have been recovered. Fish in Lake Conway have not been affected. If residents find injured or oiled wildlife, they should call the claims hotline at (1-800-876-9291) so that a trained professional can assist and minimize any potential harm. Residents are being asked not to approach wildlife for their safety and the safety of the wildlife.
- A meeting with the North Woods residents who were evacuated under a recommendation from the Arkansas Department of Health was held April 2 to convey information relative to their specific situations. A community meeting was held on March 30, less than 24 hours after the incident began, with presentations from members of the Unified Command, which includes the EPA, Arkansas Department of Environmental Quality, Arkansas Department of Health, Faulkner County, Mayflower, and ExxonMobil Pipeline Company.
- Local emergency responders from the city and county have made a tremendous contribution to the cleanup operation. The efficiency of the effort would not be possible without all the contributions of these professionals.
- Emergency response personnel were on the ground within 30 minutes after the leak was detected.
- The EPA categorizes the incident as a major spill. This category reflects a quantity greater than 250 barrels. The Unified Command now estimates approximately 5,000 barrels of oil was spilled. A final estimated release volume will be provided once the line has been repaired and refilled. A response for 10,000 barrels has been undertaken to ensure adequate resources are in place.
- The cause of the spill is under investigation.